

**PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
PART- 1**

(To be filled by the Head of School/ Institute)

1. Name of the School :- Maharishi Vidya Mandir
2. Location :- Laksar Road, Jagjit Pur
Haridwar 249 408 (Utranchal)
3. Plot Area: - 20579.26 Sqm.
4. Plinth Area: - 1608.86 Sqm.
5. Number of Storey's :- G+1 & G+2
6. Year of Construction of Building: - 2002 And III Building in 2021
7. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given
- (a) Name of the Engineer with qualification: - Sh. Rajendra Gupta (Diploma Civil Engineering)
(b) Address of Engineer: - Maihar (M.P.)
(c) Set of Structural drawings used in the construction, if available: - Available
(d) Name & address of Architect with qualification: - Sh. Arun Joshi (Architect)
N.K. Associates B-14 Alankar Place
Jwalapur HARIDWAR

8. Whether the building has been constructed for the purpose

- (a) School :- Yes
(b) Residential Purpose and converted for use as a School: - No

9. Materials used for roofs

- (a) R.C.C. Slabs/R.B.C. Slabs: - Yes
(b) R.S. Joist & Battons: - No
(c) Wooden joists & Battons:- No

10. Materials used for walls


- (a) Mud Mortar:- No
(b) Cement Mortar:- Yes
(c) Lime Mortar:- No


11. Flooring

- (a) Conglomerate:- No
(b) Terrazo:- Yes
(c) Brick Paving:- No

12. A detailed drawing indicating dimensions of the rooms Along with size and location of doors and windows


(Attached)



PRINCIPAL
MAHARISHI VIDYA MANDIR
LAKSAR ROAD, JAGJEETPUR
HARIDWAR, PIN CODE-249408


Signature with Stamp of the seal
of the School/Institution.
PRINCIPAL
Maharishi Vidya Mandir,
Jagjeetpur, Laksar Road,
Haridwar, Pincode-249408

PART-II
(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated 15.12.21..... And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used)
14.12.22.....


PRINCIPAL
MAHARISHI VIDYA MANDIR
LAKSAR ROAD, JAGJEETPUR
HARIDWAR, PIN CODE-249408

Sub Divisional Engineer

सहायक अभियन्ता
प्रांतीय ग्रंथ लो० नि० वि०
हरिद्वार